

Borough of Roselle Park
Department of Public Works
Monthly Progress Report
For
January 2018

Mayor and Council Meeting
February 1, 2018

1. **Wastewater / Stormwater Infrastructure Review:**

Sanitary Sewer: There were five (5) sewer back-ups. There were zero surcharges.

Stormwater Lines: Stormwater pipe cleaning continued as weather allowed.

2. **Generic DPW Department Responsibilities:**


- a) Continuation of faded sign replacement
- b) Continued liter pickup in downtown area.
- c) Continued white goods pickup as per taxpayer request.
- d) Continued pothole patching which will continue on weather permitting days.
- e) Street sweeping program continuing daily (weather permitting)
- f) Performing various types of tree work in Roselle Park.

3. **Non-Generic DPW Work Done:**

- 1) Exercising of the Roselle Park Generators.
- 2) Preventative Maintenance to sanitary sewer line by adding fat eater to several Locations:
 1. Westfield Ave.
 2. Chestnut Street
- 3) Took down Christmas lights at Gazebo Park, Boro Hall, and Casano Center.
- 4) Picked up 231 Christmas Trees.
- 5) Installed new shelving in the food pantry at the Casano Center.
- 6) Painted the main food pantry room at the Casano Center.
- 7) Installed new light bulbs and batteries in the exit signs at the Library, and the Casano Community Center.
- 8) Repaired the storage shed in the rear of the Center Firehouse.

- 9) Cleaned Catch Basins
- 10) Filling of Potholes
- 11) Used the TV camera truck to TV the stormwater pipe on the Corner of East Grant Ave. and Pershing Ave. and will be speaking to the Borough engineer about the problem.
- 12) Kept Roselle Park streets clean through a few snow incidents.
- 13) Performed mutual aid to Cranford because their sanitary sewer truck was being repaired.
- 14) Performed mutual aid to Cranford and TV'd one of their sanitary sewer lines with our TV Camera Truck.
- 15) Residential Calls For Service:
 - Picked up 308 Christmas trees.
 - Documented date and locations of seventeen (17) missed garbage pickups by contractor.
 - Picked up leaves at seventeen (17) locations

Respectfully Submitted,



Robert Krahnert
DPW Asst. Superintendent



Mark Pasquali
DPW Superintendent